

To: Matt Francis[m.francis@erllc.com]
From: Way, Steven
Sent: Sat 8/16/2014 12:14:38 AM
Subject: Re: Fwd: Gold King Question

Are we back to HW ?

From: Matt Francis <m.francis@erllc.com>
Sent: Friday, August 15, 2014 4:06:57 PM
To: Way, Steven
Subject: Fwd: Gold King Question

Double the estimate and it's \$4500

Sent via the Samsung Galaxy Note® 3, an AT&T 4G LTE smartphone

----- Original message -----

From: Chris Hassel
Date: 08/15/2014 4:03 PM (GMT-07:00)
To: Matt Francis
Subject: Re: Gold King Question

Ten to fifteen hours should be enough I would think.

Chris Hassel

HARRISON WESTERN CONSTRUCTION CORPORATION

1208 Quail Street
Lakewood, Colorado 80215

T (303) 302.2976 | C (720) 312.0270

F (303) 237.9868 |
www.harrisonwestern.com<<http://www.harrisonwestern.com><<http://www.harrisonwestern.com><<http://www.harrisonwestern.com>>>

Matt Francis <m.francis@erllc.com> wrote:

Help me here....Estimate the hours

Sent via the Samsung Galaxy Note® 3, an AT&T 4G LTE smartphone

----- Original message -----

From: Chris Hassel
Date: 08/15/2014 3:59 PM (GMT-07:00)
To: Matt Francis
Subject: Re: Gold King Question

We have two PE's on staff today. We could certainly turn the plans around in that time. The main

assumption would be that the materials on site will perform as new which should not be a stretch. We usually charge \$150 per hour for that kind of work.

Chris Hassel

HARRISON WESTERN CONSTRUCTION CORPORATION

1208 Quail Street
Lakewood, Colorado 80215

T (303) 302.2976 | C (720) 312.0270

F (303) 237.9868 |

[illegible]

Matt Francis <m.francis@erllc.com> wrote:

If we were to want PE stamped drawings of the support structures to meet OSHA shoring requirements is that something you could provide? If so do you have an estimate of cost and could it be done in time to mobilize by 9/10? The question arises primarily due to the portal structure being seen by some as equivalent to a field fabricated shoring system and therefore requiring blessing by a PE much like when you use something other than a manufactured trench box in an excavation.

Thanks

Confidentiality Warning: This e-mail and any attachments contain information intended only for the use of the individual or entity named above. If the reader of this e-mail is not the intended recipient or the employee or agent responsible for delivering it to the intended recipient, any dissemination, publication or copying of this e-mail is strictly prohibited. The sender does not accept any responsibility for any loss, disruption or damage to your data or computer system that may occur while using data contained in, or transmitted with, this e-mail. If you have received this e-mail in error, please immediately notify by return e-mail. Thank you

Confidentiality Warning: This e-mail and any attachments contain information intended only for the use of the individual or entity named above. If the reader of this e-mail is not the intended recipient or the employee or agent responsible for delivering it to the intended recipient, any dissemination, publication or copying of this e-mail is strictly prohibited. The sender does not accept any responsibility for any loss, disruption or damage to your data or computer system that may occur while using data contained in, or transmitted with, this e-mail. If you have received this e-mail in error, please immediately notify by return e-mail. Thank you